





Existing Site Conditions



Palisade Fence





	1	Typical Gard - concrete sle - wicking bed - 16 x rectang - 2 x pentago
	2	Accessible G - concrete sle - wicking bed - 2 x rectangu - 1 x pentago
	3	Storage Sheo - lockable me - skylight, adj - existing land
	4	Palisade Fen - tubular stee - sliding gate - sliding gate - remove x 1
	5	Vehicular Cro - concrete pa - continuous o
	6	Native Garde - edible and s - concrete sle
	7	Existing Drink - connect drip
	8	Existing Picni - review lighti
	9	Existing Perg
	10	Existing Scul
	11	Existing Feat
	12	Material Stora

CUMBERLA	16 Memorial Avenue (PO Box 42) MERRYLANDS NSW 2160 T 02 9840 9840   F 02 9840 9734	PROJECT : PEMULWUY COMMUNITY GARDEN Corner Driftway Drive and Butu Wargun Drive, Pemulwuy			TITLE : LANDSCAPE MASTER PLAN		
CITY COUN	DX 25408 MERRYLANDS TTY 02 9840 9988	DRAWN :	CHECKED :	FILE :		SCALE :	As shown @ A3
	ABN 22 798 563 329	DESIGNED :	APPROVED :	DATE : March 20	22	SHEET :	1/1

## Maataralar

Masterplan Feature	S						
len Beds eeper raised (0.5m) beds I water system gular mal							
arden Beds eeper raised (0.7m) beds water system ular nal							
tal tool storage (3.1m²) ustable shelving and double hinged doors ding pad							
ice I rod top and bottom (2.0m high) vehicular x 1 (3.2m wide) pedestrian x 2 (3.2m wide) section of blade wall							
ossover avement (3.2m wide) over utility and accessible areas							
en Beds specimen planting eeper steps							
king Fountain and Hose Tap Retained p line irrigation							
ic Table and Shelter Set Retained ing provision with sensor activation							
gola and Seating Retained							
ptures x 3 Retained							
ture Stairs Retained ver level section of blade wall							
age Bays x 3							
	(N)						
A3-LMP-01							